

Rollerco Number

Part Name

5-1060

Trimview Window Catch

## Description

Plastic window catch and spring to suit old Trimview sliding windows.

**Picture** 





## Notes / Comments

Injection moulded 1 piece catch with leaf spring included. Replacement spring is 5-1590

Unit of Supply	Recommended Maximum Load	<u>Adjustment Range</u>
Each	N/A	N/A

## **ROLLERCO**

3, 26-28 Jacobsen Crescent, Holden Hill, South Australia 5088 P: 08 8266 2554 F: 08 8266 1522 E: sales@rollerco.com.au